



# PITZ Experience with Gun5.1



Gun5 measurements and Status of L-Band conditioning facility

Mikhail Krasilnikov for the PITZ team  
XFEL MAC, 08.11.2023

HELMHOLTZ





# Gun5.1 at PITZ: Problems




# Gun5.1 at PITZ: Problems (1)

## Mini-breakdown (mBD) events



- Short ( $\sim 10\mu\text{s}$ ) interruption in RF pulse (cavity pickup and reflected power signals) + recovery within the same pulse (with a typical  $10..15\mu\text{s}$  cavity filling time)
- Majority of mBDs - in the first  $30\mu\text{s}$  of the pulse, also (seldom) at middle to end of pulse, very seldom – multiple drops
- Independent on fill/rise time ( $2..50\mu\text{s}$ ) of RF pulse ( $>300\mu\text{s}$ )
- Fast diode  $\rightarrow$  typical “switching time” of an interruption  $<100\text{ns}$
- Always accompanied by a vacuum mini-spike
- Also seen by IL sensors (VWV PMT + e-detector at the RF window, all under IL threshold)
- Source location is not clear (tests with permanent magnets  $\sim 0.4\text{T}$  around the coaxial coupler close to the gun cavity  $\rightarrow$  no dependence observed)





# Gun5.1 at PITZ: Problems (1)

## Mini-breakdown (mBD) events systematic studies

$$\frac{E_0^{30} \cdot \tau^5}{BDR} = \text{const}, \quad \text{New local field quantity describing the high gradient limit of accelerating structures}$$

A. Grudiev, S. Calatroni, and W. Wuensch  
 CERN, CH-1211 Geneva-23, Switzerland  
 (Received 28 January 2009; published 26 October 2009)



NB:  $E_{\text{cath}} \rightarrow$  beam momentum based gun power calibration





Mini-breakdown does not stop the operation, but with long RF pulses the gun RF feedback can lead to instability and even gun interlock (trip)!



# Gun5.1 at PITZ: Problems (1)





## Mini-breakdown rate (mBDR) : summary + some specific studies

- Depends on peak power, RF pulse length, repetition rate  
mBDR(1Hz) > mBDR(10Hz)
- Does not seem to be significantly improved by conditioning
- Slightly reduced using “multi-flattop” option → by lowering the 1<sup>st</sup> 100us pulse amplitude still in the first 30μs, but applied modulation in the beginning of the pulse -> mBD location shifted
- DC voltage (±25V) applied to the RF pickup → mBDR remains the same
- No dependence on gun resonance (gun temperature → reflection) observed
- increases with lower gun water temperature (cavity detuning by a phase sweep, e.g., -10°C → cavity detuning by ~-220kHz → x2 higher mBDR)







# Gun5.1 at PITZ: Problems (2)

## Cathode contact spring problem starting 31.07.2023








# Gun5.1 at PITZ: Problems (2)

Pre-history 01.07-31.07.2023



# Gun5.1 at PITZ: Problems (2)







Pre-history 01.07-31.07.2023, zoomed – week 28







# Gun5.1 at PITZ: Problems (2)

Pre-history 01.07-31.07.2023, more zoomed – weekend 14.07-17.07.2023 A.C.





# Gun5.1 at PITZ: Problems (2)

First hours run on 31.07.2023





Started with miniBDs, then...




# Gun5.1 at PITZ: Problems (2)

First hours run on 31.07.2023



# Gun5.1 at PITZ: Problems (2)

## 1<sup>st</sup> Gun trip investigation with LILI





NB: The RF probe was disconnected from measurements at this time for bias voltage tests




# Gun5.1 at PITZ: Problems (2)

1<sup>st</sup> Gun trip investigation: reflected power




# Gun5.1 at PITZ: Problems (2)

Frequent light seen at the cathode




Captured flashes during imaging of cathode


mBD(raw-bkg); EN=1760578576; 31.07.23 18:04:12




mBD(raw-bkg); EN=1760672812; 31.07.23 20:41:16



mBD(raw-bkg); EN=1762031138; 02.08.23 10:25:08





mBD(raw-bkg); EN=1762103972; 02.08.23 12:26:31






# Gun5.1 at PITZ: Problems (2)

Flashes are correlated with RF signals distortion



# Gun5.1 at PITZ: Problems (2)

Flashes are correlated with RF signals distortion




These distortions are seen by other detectors as well:

→“gamma-bursts” related to RF pulse interruptions are observed by many detectors (e.g. booster spark PDs)!




# Dark current

Even after problems started – no significant increase!



# Gun5.1 at PITZ: Problems (2)

Damage observed on the side surface of extracted cathodes (Mo#741.1 and Cs2Te#693.1)









Courtesy Frieder Müller



# Gun5.1 at PITZ: Problems (2)



Gun opened from the back (cathode) side, visual inspections on 18.08.2023 and on 23.08.2023





# Gun5.1 at PITZ: Problems (2)

Gun video inspection on 23.08.2023: positive message – no damage observed on the RF pickup




Courtesy Frieder Müller



# Gun5.1 at PITZ: Problems (2)

Damages contact spring removed





Courtesy Frieder Müller




# Gun5.1 at PITZ: Problems (2)

## Cathode area repair



2023-08-18 before spring removing



2023-08-25 after grit 1000



2023-08-25 after grit 2000


- Polishing
- 6x Grit 1000
  - 1x Grit 1500
  - 1x Grit 2000

**NB: no dry ice cleaning!**

- New contact spring inserted:
- Approx 2 windings longer than old one
  - 1st and 2nd try
- Windings never will flip in one and the same direction!



Z-actuator re-aligned



# Gun5.1 at PITZ: Problems (2)

## After mechanical repair

After mechanical repair of the cathode area:


- vacuum was closed
- pumping down
- baking
  - using gun cooling water at max, i.e. 85°C,
  - IGPs and TSP heated as well
  - cathode system ~150°C





# Gun5.1 at PITZ: Problems (2)


Reconditioning starting 12.09.2023





# Gun5.1 at PITZ: Problems (2)





Reconditioning 12.09.2023-19.10.2023



# Gun5.1 at PITZ: Problems (2)

## Observations during reconditioning

- **Extremely high dark current** (~mA at 6.7MWg), but reduced with conditioning
- Strong multipacting (MP) observed after main RF pulse → looks like conditioned out now
- No damage of cathode Mo plug after several weeks of conditioning



# Gun5.1 at PITZ: Problems (2)

## Dark current imaging

50us  
SP=60  
8.5MWg

magnets\_mainbuck\_mtca.xml PITZ.CA/MAGNETS// (on pltz-bkr...)

**main + bucking magnet**

SMAC running info: pitzoszi/unknown@znmugato41

**POLARITY**  
STATUS: opposite polarity  
magnet is in operation


MAINX: -0.3000 mm  
MAIN/Y: 0.0000 mm  
MAIN/ROLL: 0.0000 °  
MAIN/PITCH: 0.0900 °  
MAIN/YAW: 0.0050 °

500.000 MAIN (On) 470.000 469.990... (Off) 0.000

300.000 BUCKING (Off) 38.934 0.018602 (Off) 0.000

automatic: on/off, setting formula

open window for moving main magnet



magnets\_mainbuck\_mtca.xml PITZ.CA/MAGNETS// (on pltz-bkr...)

**main + bucking magnet**

SMAC running info: pitzoszi/unknown@znmugato41


**POLARITY**  
STATUS: normal polarity  
magnet is in operation

MAINX: -0.3000 mm  
MAIN/Y: 0.0000 mm  
MAIN/ROLL: 0.0000 °  
MAIN/PITCH: 0.0900 °  
MAIN/YAW: 0.0050 °

500.000 MAIN (On) 470.000 469.960... (Off) 0.000


300.000 BUCKING (Off) 38.934 0.027903 (Off) 0.000

automatic: on/off, setting formula



# Gun5.1 at PITZ: Problems (2)

Dark current imaging: looking for a FE source



# Gun5.1 at PITZ: Problems

## Summary

- Mini-breakdown events observed from the very beginning
  - Short RF pulse interruptions mostly in the first 30us, recovered with a same pulse
  - Many studies performed, but still not clear location of the problem found
- Starting 31.07.2023 – severe problems:
  - Numerous gun interlocks and trips
  - Distortions are seen by other detectors as well: “gamma-bursts” related to RF pulse interruptions are observed by many detectors (e.g. booster spark PDs)!
- Cathode side surface damage observed
- Upon opening the gun:
  - severe damage to the cathode contact spring and surrounding area observed
  - but RF pickup in the full cell looks OK
- Repair:
  - multi-step polishing, but no dry ice cleaning (significant efforts – very long shutdown)
  - new cathode contact spring (2 windings more)
  - z-actuator re-aligned
- Re-conditioning started on 12.09.2023:
  - No cathode side surface damage observed
  - Significant dark current:
    - x10 higher than before
    - Source is most probably – still contact spring area
    - reduced by conditioning but progress is now slowed down