

## Protocol

- Anusorn presents an idea to commission PIZ chicane. He and Mikhail are still waiting for a response from an expert in Hamburg. He discusses a plan for the commissioning and proposes an idea to correct trajectory and minimize effect of angle offsets at chicane entrance.
- Frank asks if we have enough steerers prior to chicane. He also asks if we can have measured field of a dipole from Hamburg. An extra HERA magnet will be combined to shims and used to measure fields. Frank suggests to use procedures used in Hamburg.
- Houjun suggests measurement of R56 and dispersion with energy scan.
- Anne forwards an old HERA cst file for future use.